

**EAST DELHI MUNICIPAL CORPORATION**  
**(ENGINEERING DEPARTMENT)**  
**OFFICE OF THE EXECUTIVE ENGINEER-M-III, SHAHDARA SOUTH ZONE**  
**SCHOOL BLOCK, SHAKARPUR, DELHI-110092**

E.E.-(M)-III-Shah. (S)/2018-2019/D- 919

dated:- 26.11.18

**Building fitness Certificate**

An application has been received in this office vide Diary no.2834 dt 31.10.2018 from the manager, Vanasthali Public School Situated at near Ruchika Petrol Pump, Mayur Vihar Phase-III, Delhi-110096 seeking building fitness certificate against the said school. Accordingly, Vanasthali Public School Situated at near Ruchika Petrol Pump, Mayur Vihar Phase-III, Delhi-110096 has been inspected for the safety point of view.

In this regard it is stated that as per visual observation the building of Vanasthali Public School Situated at near Ruchika Petrol Pump, Mayur Vihar Phase-III, Delhi-110096 is not imminent dangerous condition at present and as per appearance, site verification and structural safety certificate issued by the Architecture Er. Anil Kumar Sharma ( Sharma & Associates Govt. App. Valuer, Architect & Engineer MCD LIC NO. E-2006 & SE-0248). This certificate has no concerned with the unauthorized construction in the premises and any other dispute regarding the title of land.

Asst. Engineer M-III/SSZ

